

Notes

1.ALL SIGNS MJST COMPLY WITH THE TRAFFIC SIGNS REGULATIONS AND GENERAL DIRECTIONS 2016.
2.16M OF ROBUST INTERLOCKING BARRIER REQUIRED FOR CLOSUREPOINT.
3.RESIDENTS CAN BE ESCORTED THROUGH SITE.
4. 2X MINIMUM OPERATIVES REQUIRED TO GUARD CLOSURE POINTS.
5.70001.3A WORKFORCE IN ROAD SIGN CAN BE INSTALLED PRIOR TO 7001 MAW SIGN PLACEMENT CAN BE ACCESED ON SITE.

This Drawing is subject to Copyright and remains the property of Multevo

Sign schedule

Qty:1 Ref: 13.9 Schedule 13.4: Temporary Information	Access as far as Wall Bank no access to Church Stretton
Qty:2 Ref: 13.9 Schedule 13.4: Temporary Information	ROAD AHEAD CLOSED
Qty:2 Ref: 13.9 Schedule 13.4: Temporary Information	ROAD AHEAD CLOSED
Qty:2 Ref: 13.9 Schedule 13.4: Temporary Information	Access as far as Hope Bowdler no access to Much Wenlock
Qty:5 Ref: 2702 Start of temporary diversion route	Diversion
Qty:2 Ref: 2702 End of temporary diversion route	Diversion ENDS
Qty:6 Ref: 2702 Start of temporary diversion route	Diversion
Qty:1 Ref: 2702 Start of temporary diversion route	Diversion
Qty:17 Ref: 2703 Direction of temporary diversion route from junction ahead	Diverted traffic
Qty:2 Ref: 2703 Direction of temporary diversion route from junction ahead	Diverted traffic
Qty:2 Ref: 2703 Direction of temporary diversion route from junction ahead	Diverted traffic
Qty:1 Ref: 2703 Direction of temporary diversion route from junction ahead	Diverted traffic
Qty:5 Ref: 7001 Road works ahead	
Qty:10 Ref: 7010-FP-13-9 Nature of temporary hazard ahead - Road Ahead Closed	ROAD AHEAD CLOSED
Qty:3 Ref: 7010-FP-13-9 Nature of temporary hazard ahead - Road Closed	ROAD CLOSED

Produced by: C.Kendrick
Drawing ref:

Customer: Shropshire Highways

Location: B4371 Bank House & Woodgate Farm

Date: 28/02/24

Description: Road Closure

Diversion
Road closure
Access

Road closed here

//**** - **/**/****

for * days

MULTEVO